




RECALL NOTICE

#1 MaxCam

Batch Numbers: 0605, 0705

27 March 2006



After receiving a defective unit from a climber in the field, in-house inspection and testing has revealed that a small number of our # 1 MaxCams have head axle rivets that do not meet the minimum specified diameter, possibly resulting in failure of the cam assembly. This flaw affects only the red **#1 MaxCam** with **Batch Numbers 0605** and **0705** that were sold in 2005 and 2006. All other cams are unaffected and you can continue to use them with confidence.

Please discontinue the use of **#1 MaxCams** from **Batch Numbers 0605** and **0705** from use immediately and return them according to the instructions below. We highly recommend that you use UPS or FedEx so that you have a tracking number.

Via UPS/FedEx or other package service	Via US Mail (USPS)
TMI/Trango Freeport Center F-11 Clearfield, UT 84016	TMI/Trango PO Box 160470 Clearfield, UT 84016

We will inspect and repair or replace your MaxCams within three business days and return them to you. Mark each cam with a return address, a phone number and an email where we can reach you if we have questions.

We are truly sorry for any inconvenience. Please call us at 800/860-3653 or visit our website at www.trango.com if you have any further questions.

Climb Safe,

Malcolm Daly, Director
mdaly@trango.com